

Illustrated Parts List - IPL Update



Product Name(s)

Husqvarna 450e II

Description of change

1. We have improved Starter Pulley Kit 586 65 95-03. The pulley and driver has been improved due to issues with the assisting spring slipping when pulling the rope.
2. Starter Housing 505 42 28-02, change of supplier.

Comments

This update is fully exchangeable. **Note:** Starter Pulley Kit 586 65 95-03 cannot be mixed with subcomponents in Starter Pulley Kit 586 65 95-02.

Introduced from

Serial number / Date	Remark
s/n 20184800041	Valid for Starter Assy, 579 42 53-11. North America
s/n 20184800192	Valid for Starter Assy, 579 42 53-11. RoW
s/n 20184800041	Valid for Starter Pulley, Kit 586 65 95-03. North America
s/n 20184900192	Valid for Starter Pulley, Kit 586 65 95-03. RoW
	Starter Housing 505 42 28-02.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Starter	1	579 42 53-11	Starter Assy	579 42 53-07	
	2	505 42 28-02	Starter Housing	586 69 02-02	Minor correction.
	15	586 65 95-03	Starter Pulley Kit	586 65 95-02	