

Illustrated Parts List - IPL Update



Product Name(s)

372 XP

Description of change

1. Brake Spring changed to a stronger variant.
2. Clutch Drum get new part number.
3. Screw for Ignition Module changed for better grip.
4. Nut for flywheel changed to avoid for high torque.
5. Washer added to flywheel to avoid for high torque.

Comments

All updates are fully interchangeable

Introduced from

Serial number / Date	Remark
20144500001-	Brake Spring 503 70 99-02
20144400769-	Clutch Drum 586 98 06-01
20144400769-	Clutch Drum 586 98 06-02
20150700769-	Screw lhscm 586 28 93-01
20151100001-	Nut 503 22 10-11
20151100001-	Washer 503 23 01-01

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Chain Brake & Clutch Cover	11	503 70 99-02	Brake Spring	503 70 99-01	
Clutch & Oil Pump	17	586 98 06-01	Clutch Drum	503 93 24-71	
Clutch & Oil Pump	17	586 98 06-02	Clutch Drum	503 93 24-72	
Ignition System	3	586 28 93-01	Screw lhscm	503 20 02-20	
Ignition System	8	503 22 10-11	Nut	503 22 04-01	
Ignition System	14	503 23 01-01	Washer		