

Illustrated Parts List - IPL Update



Product Name(s)

390 XP

Description of change

New hose clamp with curved edges for elimination of crack in inlet pipe.

Comments

Fully interchangeable

Introduced from

Serial number / Date	Remark
20155100001 -	Hose clamp 588 77 55-01

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Carburettor & airfilter	10	588 77 55-01	Hose clamp	505 28 33-02	

Hose clamp



588 77 55-01

Hose clamp



505 28 33-02