

Illustrated Parts List - IPL Update



Product Name(s)

525 HF3S

Description of change

1. New ignition coil.
2. Diameter reduced on spring wire. Same function but easier to assemble in spark plug cap.

Comments

Backward compatible.

Introduced from

Serial number / Date	Remark
2015-02	Ignition coil 588 14 12-01
2015-02	Spring 588 17 62-01

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition system and clutch	1	588 14 12-01	Ignition coil	587 52 78-01	
Ignition system and clutch	5	588 17 62-01	Spring	587 52 79-01	