

# Illustrated Parts List - IPL Update



Product Name(s)

**525RX**

Description of change

1. Uniting of several different article numbers to one.
2. Change of bearing regarding quality.

Comments

Fully exchangeable

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
	Ignition cable 584 82 66-01
	Bearing 506 61 03-01

IPL updates

<b>Page Title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Ignition system and clutch	2	584 82 66-01	Ignition cable	576 88 27-01	
Crankshaft	5	506 61 03-01	Bearing	523 07 17-01	