

# Illustrated Parts List - IPL Update



Product Name(s)

525LK

Description of change

New ignition coil.

Comments

Backward compatible.

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
2015-02	Ignition coil 588 14 15-01

IPL updates

<b>Page Title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Ignition system and clutch	1	588 14 15-01	Ignition coil	576 40 39-01	