

Illustrated Parts List - IPL Update



Product Name(s)

525LST

Description of change

1. Uniting of several different article numbers to one.
2. Change of bearing regarding quality.

Comments

Fully exchangeable

Introduced from

Serial number / Date	Remark
	Ignition cable 584 82 66-01
	Bearing 506 61 03-01

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition system and clutch	2	584 82 66-01	Ignition cable	576 88 27-01	
Crankshaft	5	506 61 03-01	Bearing	523 07 17-01	