

Illustrated Parts List - IPL Update



Product Name(s)

122HD45

Description of change

Increased spark duration time. Better runability and reduced time for the warm-up of engine.

Comments

Fully interchangeable.

Introduced from

Serial number / Date	Remark
2019-06	Ignition module 585 07 40-02

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition System	8	585 07 40-02	Ignition module	525 87 33-01	