

Illustrated Parts List - IPL Update



Product Name(s)

H555

Description of change

1. A new Inlet pipe, assy 583 96 41-03/-04 have been introduced. The change has been made to ensure the assembly and to avoid leakage.
2. The New Carburetor, kit 501 46 33-06 consist of: New Carburetor ZAMA140059A, a separate support sleeve 582 02 51-01 and AT-instruction.
3. New article number and some minor changes on Air Nozzle due to change of supplier.

Comments

This update is fully exchangeable.

Introduced from

| Serial number / Date | Remark |
|-------------------------|---|
| s/n 2018 5100289 | Valid for Carburetor Kit, Flange, Support sleeve and Inlet pipe assy. |
| s/n 20171700154 | Valid for Air nozzle. |
| | |
| | |


IPL updates

| Page Title | Ref . no | New part no | Name | Excl. part no. | Remark |
|-------------------------|----------|--------------|-----------------|----------------|------------------------|
| Carburetor Details | 1 | 501 46 33-06 | Carburetor, kit | 501 46 33-04 | |
| Carburetor & Air filter | 10 | 501 46 33-06 | Carburetor, kit | 501 46 33-04 | |
| | 12 | 505 16 52-02 | Flange | 505 16 52-01 | |
| | 14 | 583 96 41-03 | Inlet pipe | 583 96 41-01 | |
| | 14 | 583 96 41-04 | Inlet pipe | 583 96 41-02 | Cold resistant |
| | 21 | 582 02 51-01 | Support Sleeve | | New Spare part. |
| Crankcase | 24 | 588 06 55-01 | Air nozzle | 520 29 12-01 | |
| | | | | | |

Illustrated Parts List - IPL Update


1. Carburetor

New version



501 46 33-06, ZAMA140059A

Old version



501 46 33-04, ZAMA140056A

