

Illustrated Parts List - IPL Update



Product Name(s)

562XP / 562XPG

Description of change

1. Inlet Pipe: Cold-resistant material for extreme conditions.
2. Ignition module "s/n up to - 20121401172": New, updated with improved startability.
3. Diagnostic tool kit: New article number for the kit. A New cable for the battery products added into the kit.
4. New article number on the sleeve for old Muffler design.

Comments

Introduced from

Serial number / Date	Remark
20134400001	Inlet pipe 5839641-02 valid for PNC 9665702-00 (Russia).

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Carburetor and Air filter	14	5839641-02	Inlet pipe		
Ignition system	1	5227951-06	Ignition module	5227951-02	Spare part only.
Accessories	7	5838971-01	Diagnostic tool kit	5766923-01	
Muffler	5	5776563-01	Sleeve	5769552-01	Spare part only.