

Illustrated Parts List - IPL Update



Product Name(s)

455 Rancher II

Description of change

1. New Fuel hose, changed material
 2. New Flywheel assy, new supplier, same design
 3. Auto tune spare part kit, 5777970-01 removed as a spare part due to coordination with products. This also include the screw and gasket

	Serial number / Date	Remark
Introduced from		
Fuel hose	20132700001	

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Fuel tank	4	581 75 62-02	Fuel hose	544 32 50-02	
Ignition system	1	580 38 92-01	Flywheel assy	574 67 76-01	
Carburettor details		577 79 70-01	Auto Tune spareparts kit		Removed
Carburettor details		574 35 91-01	Screw		Removed
Carburettor details		574 35 87-01	Gasket		Removed

Comments