

# Illustrated Parts List - IPL Update



Product Name(s)

**H455 RANCHER II**

Description of change

New Starter pulley added.

Comments

Fully interchangeable

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
S/n 20151000001	New Starter pulley 537 09 25-02 added.
2015-07-01	New Starter pulley 537 09 25-02 added. North America.

IPL updates

<b>Page Title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Starter	6	5370925-02	Starter pulley	5370925-01	