

Illustrated Parts List - IPL Update



Product Name(s)

H455E

Description of change

New resistor plug is implanted in production due to cost reduction.

Comments

Fully interchangeable.

Introduced from

Serial number / Date	Remark
2017-03-23	

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Cylinder & Piston	3	577 48 40-01	Spark plug	503 23 51-08	Remain as spare part.