

Illustrated Parts List - IPL Update



Product Name(s)

H555

Description of change

A new clutch drum, assy is introduced to avoid the chain touching the drum.
 1. A chamfer has been added to clutch drum edge. 2. Bearing seat tolerances are adjusted.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20173700001	Valid for Clutch drum, assy 575 26 10-05 .325" x 7T.
s/n 20174000182	Valid for Clutch drum, assy 575 26 10-06 3/8" x 7T.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Clutch & Oil pump	3	575 26 10-05	Clutch drum, assy	575 26 10-03	.325"
	3	575 26 10-06	Clutch drum, assy	575 26 10-04	3/8"