

# Illustrated Parts List - IPL Update



Product Name(s)

**365SP**

Description of change

1. Incorporation of new Fuel tank.  
Reason: New tank vent assy.
2. New spare part: Tank vent assy 501 15 29-01

Comments

Up to serial number 20184700378: 537 09 93-01\* Connection bend  
Up to serial number 20184700378: 537 09 22-01\* Tank vent assy

From serial number 20184700379: 501 15 29-01 Tank vent assy

Introduced from

| Serial number / Date     | Remark                      |
|--------------------------|-----------------------------|
| 20184700379 / 2018-11-20 | Fuel tank 544 11 40-13      |
| 20184700379 / 2018-11-20 | Tank vent assy 501 15 29-01 |
|                          |                             |

IPL updates

| Page Title | Ref. No | New part no  | Name            | Excl. part no. | Remark                 |
|------------|---------|--------------|-----------------|----------------|------------------------|
| Fuel tank  | 1       | 544 11 40-13 | FUEL TANK       | 544 11 40-07   |                        |
|            | 3       | -            | CONNECTION BEND | 537 09 93-01*  | *Remain as spare part. |
|            | 4       | 501 15 29-01 | TANK VENT ASSY  | 537 09 22-01*  | *Remain as spare part. |



# Illustrated Parts List - IPL Update

## 1. Fuel tank

New




Old



501 15 29-01 Tank vent assy replaces 537 09 22-01\* Tank vent assy (pos. 4).

537 09 93-01\* Connection bend removed (pos. 3).

*\*Remains as spare part.*



544 11 40-13 Fuel tank replaces 544 11 40-07 Fuel tank (pos. 1).