

Illustrated Parts List - IPL Update



Product Name(s)

572 XP/XPG

Description of change

New oil hose for oil pump.
Reason: Increased sealing function against the oil housing.

Comments


Introduced from

Serial number / Date	Remark
183200037 / 2018-08-15	OIL HOSE ASSY 594 09 32-01

IPL updates

Page Title	Ref. No	New part no	Name	Excl. part no.	Remark
Clutch & Oil pump	14	594 09 32-01	OIL HOSE	588 40 47-01	

1. Clutch & Oil pump



Changed oil hose to 594 09 32-01 (pos. 14).